

### **ABSTRACT OF THE DISCLOSURE**

A method for measuring current leakage of a contact of a semiconductor device formed on or in a substrate, includes scanning the contact with a probe of a conductive atomic force microscope; applying a DC voltage between the substrate and a conductive tip of the probe; and measuring a value of a current passing through the contact to the substrate, in response to the applied DC voltage.